

9: ROOF

9.1	Front Slope
9.2	Right Slope
9.3	Back Slope
9.4	Left Slope

Information

Front Slope: Test Square



Front Slope: Impact Assessment
15+



Right Slope: Test Square



Right Slope: Roof Components
Pipe Jack

Back Slope: Impact Assessment
15+



Back Slope: Test Square





9.2.1 Right Slope

HAIL DAMAGE

 Recommendation

There appeared to be hail damage during the time of inspection.



Hail damage is the result of hailstones impacting a surface, causing varying degrees of harm, including dents, cracks, bruises or fractures, typically observed on roofing materials, siding, windows, and gutters, etc.

Haag Engineering defines hail damage as: Physical damage caused by hailstone impact that results in the loss of granules, bruising, fracturing, or puncturing of the shingle mat, which may affect the shingle’s ability to shed water or reduce its expected service life.

Recommendation

Contact a qualified gutter contractor







Line Type		Total Length (ln.ft)	Line Type		Total Length (ln.ft)
Ridge	●	127.42	Rake	●	158.33
Hip	●	0.00	Eave	●	193.67
Valley	●	45.67	Apron Flashing	●	71.00
Penetration		0	Step Flashing	●	0.00

Pitch	Area (SQ)	% of Roof
4/12	39.62	100.00

This report is for estimation purposes only. Please make sure to verify all roof details, obstacles, slopes, dimensions prior to material ordering.







Line Type		Total Length (ln.ft)	Line Type	Total Length (ln.ft)
Ridge	●	127.42	Rake	158.33
Hip	●	0.00	Eave	193.67
Valley	●	45.67	Apron Flashing	71.00
Penetration		0	Step Flashing	0.00

Pitch	Area (SQ)	% of Roof
4/12	39.62	100.00

This report is for estimation purposes only. Please make sure to verify all roof details, obstacles, slopes, dimensions prior to material ordering.





Line Type		Total Length (ln.ft)	Line Type		Total Length (ln.ft)
Ridge	●	127.42	Rake	●	158.33
Hip	●	0.00	Eave	●	193.67
Valley	●	45.67	Apron Flashing	●	71.00
Penetration		0	Step Flashing	●	0.00

Pitch	Area (SQ)	% of Roof
4/12	39.62	100.00

This report is for estimation purposes only. Please make sure to verify all roof details, obstacles, slopes, dimensions prior to material ordering.





Line Type		Total Length (ln.ft)	Line Type		Total Length (ln.ft)
Ridge	●	127.42	Rake	●	158.33
Hip	●	0.00	Eave	●	193.67
Valley	●	45.67	Apron Flashing	●	71.00
Penetration		0	Step Flashing	●	0.00

Pitch	Area (SQ)	% of Roof
4/12	39.62	100.00

This report is for estimation purposes only. Please make sure to verify all roof details, obstacles, slopes, dimensions prior to material ordering.